## **Area Source Workshop Agenda**

## January 8, 2014

8:00 – 8:30	Registration	
8:30 - 8:35	Logistics Information	Division of Compliance Assistance
8:35 – 8:45	Attendee Introductions	Division of Compliance Assistance
8:45 – 9:15	Boiler Area Source Rule	Division of Air Quality
9:15 – 10:00	Emission Limit Requirements	Division of Air Quality
10:00 – 10:15	Break	
10:15 – 11:00	Tune Up Requirements	Division of Compliance Assistance
11:00 – 11:45	Energy Assessment Requirements	Kentucky Pollution Prevention Center
11:45 – 12:00	Questions and Wrap Up	